

TECHNICAL BULLETIN

20/01



Falcon Foodservice Equipment
Wallace View
Hillfoots Road
Stirling
Scotland. FK9 5PY
Tel: 01786 455200
Fax: 01786 469454
info@falconfoodservice.com
www.falconfoodservice.com

G3101/61/07/17/D/HD Oven Ranges G3845/30/60/65/F & G1808/38/48X Fryers

NEW SPARK IGNITER

The Spark Igniter is now obsolete and has been replaced.

535010000: Ø22mm Spark Igniter– OBSOLETE



535290100: Ø18mm Spark Igniter kit – Replacement



OVEN RANGES

To replace Oven Range Full Ignition Kit Pre F551159

535241012 & 535290052 - OBSOLETE

535290101: Oven Ignition Kit Pre F551159 - Replacement

To replace Oven Range Full Ignition Kit Post F551159

535290067 - OBSOLETE

535290102: Oven Ignition Kit Post F551159 - Replacement

To replace Oven Spark Electrode Assembly Pre Feb 2020

535290059: Oven Burner Electrode Assembly c/w Lead

To replace Oven Spark Electrode Assembly Post Feb 2020

535290103: Oven Burner Electrode Assembly c/w Lead

FRYERS

To Replace Fryer Ignition Kit - G3830/60/65/F & G1808/38/48X

535670026 & 535710135 - OBSOLETE

535580080: Fryer Ignition Kit - Replacement

To Replace Fryer Ignition Kit - G3845/F

535620011: Fryer Ignition Kit