

TECHNICAL BULLETIN

24/02



G3830/60/65 FRYERS G3860F/65F FRYERS G3845 & F FRYERS G1808X/38X/48X FRYERS

Falcon Foodservice Equipment
Wallace View
Hillfoots Road
Stirling
Scotland. FK9 5PY
Tel: 01786 455200
Fax: 01786 469454
info@falconfoodservice.com
www.falconfoodservice.com

From August 2024, Falcon will be changing the Maxitrol gas valve which is fitted to the above fryers detailed


The original GV30A Gas Valve fitted to the Fryers above will no longer be available and all new units manufactured will now be fitted with a GV30T Gas Valve.

The Spare No's for the new GV30T valves for new production units are as follows:

G3830, G3865, G3865F, G1808X & G1848X	– 535540000
G3860, G3860F & G1838X	– 535550000
G3845 & G3845F	– 535630000

For units built prior to August 2024, that haven't already been converted, a valve replacement kit will require to be ordered.

In order to ascertain which valve is fitted, this can be done by looking at the valve and checking them in line with the diagrams below, with the difference being with the markings and size of the lighting position knob:



GV30A Maxitrol fitted to units
pre August 2024

GV30T Maxitrol fitted to units
post August 2024

The part numbers for the kits for units manufactured prior to August 2024 are as follows:

G3830 & G3865	–	535570020
G3860	–	535580085
G3860F	–	535580086
G3865F	–	535590086
G3845	–	535620030
G3845F	–	535620031
G1808X & G1848X	–	537580020
G1838X	–	537590025

These spares kits will be supplied with all necessary parts and full fitting instructions

All previous part numbers, listed below, for the GV30A Maxitrol valves will now be obsolete

G3860	-	535580012
G3860F	-	535580061
G3830 & G3865	-	535580017
G3865F	-	535590012
G3845 & G3845F	-	535620016